

Comers run from	Comers run to	No. ch.	Comers run from	Comers run to	No. ch.
Section 13 Township 7 Range 3					
February 27 th 1879 Surveyed in Section 13					
N 6° 4' 27"	E 1/4	40.18 1/2	E 1/4	SE	40.18 1/2
SE 4° 18'	S 1/4	39.58	S 1/4	SW	39.58
N 6° 4' 55"	N 1/4	39.64	NW	W 1/4	39.86
W 1/4 4° 25'	SW	39.86			

W. W. Clogston

Cor Est.	No. of Cor.	Bearing	Dist.	Courses	Dist.	Bearing	Dist.	Courses	Dist.
For Calvin Sparks									
Down 7 Range 3									
Q 1/4 NW 1/4		Buck	20	N 21 W	34 1/2				
Q 1/4	Stone	Stone		N 71 W	44 1/2				
Q 1/4 SE 1/4	Stone	Sycamore	10	S 13 1/2 W	70				
SE cor	"	Beech	16	S 65 W	47	Buck	22	S 85 W	99
S 1/4 SE 1/4	"	Cypress	12	S 30 W	28	W. Oak	20	S 29 E	14
Q 1/4	"								
Q 1/4 SW 1/4	"	W Oak	20	S 17 E	53				
SW corner	"	"	36	S 86 E	37	Buck	28	S 67 E	39 1/2
W 1/4 SW 1/4	"	"	20	S 89 W	11	W. Oak	24	N 5 1/2 E	11
W 1/4	"	"	20	S 23 W	26	Poplar	24	N 46 1/2 W	80
W 1/4 NW 1/4	"	Poplar	9	S 55 E	86				
Centre 1/4	Stone	B. Walnut	15	S 30 1/2 E	97				
N 1/4	"	Elm	10	N 61 1/2 W	17				
Q 1/4 NW 1/4	Stone	W Oak	24	S 34 1/2 E	27				
Q 1/4 NW 1/4	"	"	24	N 62 E	83	Sugar	24	S 46 E	86 1/2
Centre NW 1/4	"	Elm	28	N 30 1/2 W	45	Poplar	8	N 75 W	44
Q 1/4 SW 1/4	"	W Oak	30	N 49 W	26 1/2	W Oak	26	N 29 W	41 1/2
Centre SW 1/4	"	Stone		N 6 W	26				
Centre SE 1/4	"	Buck	12	N 29 W	30 1/2	Buck	10	N 4 1/2 W	26
W 1/4 NW 1/4	"	"	20	S 54 W	28	Poplar	8	N 6 1/2 W	31
Centre NW 1/4	"	No trees near							

Section 27 Township 6 Range 3

March 29th 31st Apr 12, 1879

Surveyed for Ben, George Charles Strosnider and Wm Winder to ascertain the corner from which the town of Owensburg was laid out. Said corner being E 1/4 SW 1/4 of Section 27. To NW 3/4 beginning at SE cor of sd sec. thence west to SW corner went each half a mile run N 20 ch. Found corner by excavation, then measured 15 feet north to centre of street. Thence proceeded to survey by running along the street N 49° W and surveyed the lots Wm Winder, Charles Strosnider. Mr. Francis on the south side of street and for Ben George and

John Beaty and Peter Lehman on North side
Francis M. Parker
Co. Sur.

Note:-

This survey corresponded with main street as improved but lines at right angles did not. There seems to have been a mistake or misunderstanding of the plat.